

5511029

00/246,502

FIG. 1





FIG. 2



APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

FIG. 3




FIG. 4






FIG. 5



APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

FIG. 6




APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

FIG. 7



FUNCTION	/CS	/RAS	/CAS	/WE	DQM
ROW ADDRESS STROBE AND ARRAY ACTIVATION	L	L	H	H	—
COLUMN ADDRESS STROBE AND READ	L	H	L	H	—
COLUMN ADDRESS STROBE AND WRITE	L	H	L	L	—
PRECHARGE / SELF REFRESH END	L	L	H	L	—
REFRESH / SELF REFRESH START	L	L	L	H	—
SET MODE REGISTER	L	L	L	L	—
WRITE ENABLE / OUTPUT ENABLE	—	—	—	—	L
WRITE MASK / OUTPUT DISABLE	—	—	—	—	H
NO CHANGE	L	H	H	H	—
IGNORE /RAS, /CAS & /WE	H	X	X	X	—

FIG. 8



APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

FIG. 9








FIG. 11

FIG. 13




APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

FIG. 14



APPROVED	O.G. FIG.	
BY .	CLASS	SUBCLASS
DRAFTSMAN		

FIG. 15







FIG. 16

FIG. 17






FIG. 18

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		




FIG. 19

FIG. 20





FIG. 21






FIG. 24

	/RDT N/P <0:7>	NO1	NO2	DDFT	DECISION
PRECHARGE	L/H	H	L	-	-
ALL "H"	L	H	H	H	PASS
ALL "L"	H	L	L	H	
"H" AND "L"	H & L	L	H	L	FAIL

FIG. 25




FIG. 26




FIG. 27




FIG. 28




FIG. 29




FIG. 30




FIG. 31




FIG. 32




FIG. 33




FIG. 34




FIG. 35







FIG. 36



APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

FIG. 37



APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

FIG. 39

